

TAWARAN SEBUTHARGA

1. **TAJUK** KERJA-KERJA PENYELENGGARAAN DAN PEMBAIKAN SISTEM
SEBUTHARGA: PENGHAWA DINGIN DI BANGUNAN PEJABAT KASTAM PORT
 KLANG FREE ZONE SDN BHD
NO. RUJUKAN: PKFZ/RFQ/9/2020/023(FMD)
KELAYAKAN CIDB
KONTRAKTOR: KOD M01

NO	PERKARA	KUANTITI
1	<p><u>L1-1</u> Location: Pantry Type: Wall Mounted HP: 2.5 Brand: Daikin</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1
2	<p><u>L1-8B</u> Location: Office Area Type: Cassette HP: 2.5 Brand: Trane</p> <p>Indoor & Outdoor</p> <ul style="list-style-type: none"> - Air Conditioner system is not functioning and need to conduct detailed troubleshooting and fault rectification 	1
3	<p><u>L1-9B</u> Location: Office Area Type: Cassette HP: 2.5 Brand: Trane</p> <p>Indoor & Outdoor</p> <ul style="list-style-type: none"> - Air Conditioner system is not functioning and need to conduct detailed troubleshooting and fault rectification 	1
4	<p><u>L1-11A</u> Location: Utility Room Type: Cassette HP: 2.5 Brand: Trane</p> <p>Indoor & Outdoor</p> <ul style="list-style-type: none"> - Air Conditioner system is not functioning and need to conduct detailed troubleshooting and fault rectification 	1

NO	PERKARA	KUANTITI
5	<p><u>L1-11B</u> Location: Office Area Type: Cassette HP: 2.5 Brand: Trane</p> <p>Indoor & Outdoor - Air Conditioner system is not functioning and need to conduct detailed troubleshooting and fault rectification</p>	1
6	<p><u>L1-13A</u> Location: Office Area Type: Cassette HP: 2.5 Brand: Daikin</p> <p>Indoor - Chemical Service - Inspect Blower Motor</p> <p>Outdoor - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp</p>	1
7	<p><u>L1-13B</u> Location: Office Area Type: Cassette HP: 2.5 Brand: Trane</p> <p>Indoor & Outdoor - Air Conditioner system is not functioning and need to conduct detailed troubleshooting and fault rectification</p>	1
8	<p><u>L1-20</u> Location: Office Area Type: Cassette HP: 2.5 Brand: Trane</p> <p>Indoor & Outdoor - Air Conditioner system is not functioning and need to conduct detailed troubleshooting and fault rectification</p>	1

NO	PERKARA	KUANTITI
9	<p><u>L1-21</u> Location: Office Area Type: Cassette HP: 2.5 Brand: Trane</p> <p>Indoor & Outdoor</p> <ul style="list-style-type: none"> - Air Conditioner system is not functioning and need to conduct detailed troubleshooting and fault rectification 	1
10	<p><u>L1-22</u> Location: Room No.9 Type: Wall Mounted HP: 2.0 Brand: Trane</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Replace Cooling Coil Sensor - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1
11	<p><u>L1-23</u> Location: Room No.8 Type: Wall Mounted HP: 2.0 Brand: Trane</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1

NO	PERKARA	KUANTITI
12	<p><u>L1-24</u></p> <p>Location: Room No.7 Type: Wall Mounted HP: 2.0 Brand: Trane</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Replace Cooling Coil Sensor - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1
13	<p><u>L1-25</u></p> <p>Location: Room No.6 Type: Wall Mounted HP: 2.0 Brand: Trane</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1
14	<p><u>L1-26</u></p> <p>Location: Room No.5 Type: Cassette HP: 3.0 Brand: Daikin</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1

NO	PERKARA	KUANTITI
15	<p><u>L1-27</u></p> <p>Location: Room No.4 Type: Cassette HP: 2.5 Brand: Daikin</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1
16	<p><u>L1-28B</u></p> <p>Location: Meeting Room Type: Cassette HP: 2.5 Brand: Trane (Existing)</p> <ul style="list-style-type: none"> - Replace New Unit - Suggesting Brand Daikin 2.5HP Non-Inverter 	1
17	<p><u>L1-28A</u></p> <p>Location: Meeting Room Type: Cassette HP: 2.5 Brand: Trane (Existing)</p> <ul style="list-style-type: none"> - Replace New Unit - Suggesting Brand Daikin 2.5HP Non-Inverter 	1
18	<p><u>L1-29</u></p> <p>Location: Server Room Type: Wall Mounted HP: 2.0 Brand: York (Existing)</p> <ul style="list-style-type: none"> - Replace New Unit - Suggesting Brand Daikin 1.5HP Non-Inverter 	1

NO	PERKARA	KUANTITI
19	<p><u>L1-29 (Additional New Unit)</u></p> <p>Location: Server Room Type: Wall Mounted HP: 1.5 Brand: Daikin (Suggest)</p> <ul style="list-style-type: none"> - Install new additional unit. - Suggesting Brand Daikin 1.5HP Non-Inverter - Install timer control panel with time setting 5 hours for each air conditioner for alternate run - Wiring for new timer control panel - Wiring for new additional air-cond 	1
20	<p><u>L1-PR1</u></p> <p>Location: Male Prayer Room Type: Cassette HP: 2.5 Brand: Trane</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1
21	<p><u>L1-PR2</u></p> <p>Location: Female Prayer Room Type: Cassette HP: 2.5 Brand: Trane</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1

NO	PERKARA	KUANTITI
22	<p><u>CUSTOM GATE BOOTH</u></p> <p>Location: Booth No. 7 Type: Wall Mounted HP: 1 Brand: York</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1
23	<p><u>CUSTOM GATE BOOTH</u></p> <p>Location: Booth No. 8 Type: Wall Mounted HP: 1 Brand: York</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1
24	<p><u>CUSTOM GATE BOOTH</u></p> <p>Location: Booth No. 9 Type: Wall Mounted HP: 1 Brand: York</p> <p>Indoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Blower Motor condition <p>Outdoor</p> <ul style="list-style-type: none"> - Chemical Service - Inspect Fan Motor - Check Refrigerant Level - Check Compressor Abnormal Noise and Compressor Amp 	1

NOTA:

1. Perkhidmatan dan Barangan yang dibekalkan hendaklah diberikan **Tempoh Jaminan** produk.
2. Kerja-kerja yang telah dilaksanakan perlu diberikan **Tempoh Tanggungan Kecacatan** selama **6 hingga 12** bulan berkuatkuasa dari tarikh siap kerja.
3. Penyebutharga dikehendaki membuat **Lawatan Tapak** terlebih dahulu sebelum memberikan tawaran harga bagi kerja-kerja yang melibatkan teknikal.
4. Sebutharga perlu lengkap dengan **nama syarikat dan alamat, no. telefon, alamat emel** dan perlu melampirkan **profil syarikat**.
5. Setiap sebutharga yang telah lengkap perlu di hantar melalui emel ke alamat surayah@pkfz.com atau dimasukkan ke dalam peti sebutharga di pejabat PKFZ lengkap dengan sampul surat yang beralamat:

Port Klang Free Zone Sdn Bhd

Jalan FZ 2-P5,

Port Klang Free Zone / KS 12,

42920 Pulau Indah,

Selangor Darul Ehsan

6. Sebarang pertanyaan boleh diajukan kepada **Urusetia Perolehan, PKFZ: 03-3101 5568**.
7. **Sah Laku** tawaran ini adalah **7** hari berkerja dari tarikh diiklankan.